

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION AGREEMENT  
(SAMPLE REPORT)**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

**BUYER / CLIENT INFORMATION:**

**REALTOR INFORMATION**

NAME:

NAME:

ADDRESS:

REALTY CO

ADDRESS:

CELL / WORK PHONE:

PHONE

HOME PHONE

FAX / E-MAIL:

FAX / E-MAIL:

---

**PROPERTY INFORMATION:**

**TYPE OF INSPECTION REQUESTED:**

ADDRESS:

STRUCTURAL:      XX

MECHANICAL:      XX

COUNTY              HARRIS

POOL:

KEY MAP NO.

SPA:

TYPE OF STRUCTURE:      SFH

OTHER:

APPROX. AGE OF STRUCTURE:      NEW

---

**TOTAL INSPECTION FEE \$      (TO BE PAID AT TIME OF INSPECTION)**

**IMPORTANT NOTICE: (PLEASE READ CAREFULLY)**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION AGREEMENT**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

**VACANT HOUSES:**

**THE FOLLOWING ITEMS ARE THE MOST COMMON PROBLEMS FOUND AFTER A HOUSE HAS BEEN VACANT FOR A WEEK OR MORE; AND ALLIED HOME INSPECTION SERVICES WILL NOT BE RESPONSIBLE FOR:**

- 1. SEWER AND DRAIN LINES STOPPING UP AND LEAKS AT FAUCETS DUE TO SEALS AND WASHERS DRYING OUT.**
- 2. LEAKS AT DISHWASHERS (SEALS DRYING OUT), DISHWASHER MOTOR OR PUMP LOCKING UP**
- 3. GARBAGE DISPOSAL LOCKING UP.**
- 4. WATER HEATERS LEAKING AT DRAIN VALVE AND/ OR SUPPLY LINE**
- 5. DAMAGE TO ELECTRIC WATER HEATERS WHEN WATER IS DRAINED FROM WATER HEATER BUT ELECTRIC POWER IS NOT SHUT OFF TO WATER HEATER. (CAUSES DAMAGE TO HEATING ELEMENTS AND THERMOSTATS.**
- 6. GAS WATER HEATERS AND GAS FURNACES. (IF GAS HAS BEEN TURNED OFF, THERMOCOUPLE (PILOT GENERATOR) MAY FAIL.**

**STRUCTURAL & MECHANICAL INSPECTIONS DO NOT INCLUDE THE FOLLOWING: GAS LINES, OUTDOOR COOKING EQUIPMENT, YARD LIGHTING, FRENCH DRAIN SYSTEMS, SECURITY & FIRE SYSTEMS, WATER WELL SYSTEMS, SEPTIC SEWAGE SYSTEMS, SELF-CLEANING CYCLE ON OVENS, RADIATION LEAKAGE FROM MICROWAVE OVENS, OR RISER HEIGHT ON STAIRWAYS.**

**STRUCTURAL & MECHANICAL INSPECTIONS DO NOT INCLUDE THE DETERMINATION OF THE PRESENCE OF ANY WOOD-DESTROYING INSECTS, ASBESTOS CONTAINING MATERIALS, RADON, LEAD PAINT, ON ANY TYPE OF CHEMICAL OR CARCINOGENIC SUBSTANCE OR GAS THAT IS HARMFUL TO HUMANS OR ANIMALS INCLUDING MOLD, FUNGI, OR OTHER MICROBES.**

**IMPORTANT INSPECTION LIMITATIONS AND DISCLAIMERS**

**THIS INSPECTION REPORTS ONLY ON THE ITEMS LISTED AND ONLY ON THE PRESENT CONDITION OF THOSE ITEMS. THIS INSPECTION REPORT REFLECTS ONLY IF THE ITEMS INSPECTED ARE OBSERVED TO BE "FUNCTIONAL" OR "IN NEED OF REPAIR" AT THE TIME OF THE INSPECTION. THAT IS, WHETHER SUCH ITEMS AT THE TIME OF THE INSPECTION ARE OBSERVED TO BE SERVING THE PURPOSE FOR WHICH THEY ARE ORDINARILY INTENDED. THIS INSPECTION IS NOT A CODE INSPECTION. THIS INSPECTION REPORT REFLECTS ONLY THOSE ITEMS REASONABLY OBSERVABLE AT THE TIME OF THE INSPECTION. NO REPRESENTATION OR COMMENT CAN BE MADE CONCERNING ANY LATENT DEFECTS OR DEFECTS NOT REASONABLY OBSERVABLE BY THIS INSPECTOR AT THE TIME OF THE INSPECTION OR OF OTHER ITEMS WHICH REQUIRE THE REMOVAL OF PERMANENT COVERINGS. THIS INSPECTOR IS RENDERING OPINIONS ON THE CONDITION OF THE PROPERTY AT THE TIME OF THE INSPECTION. THIS IS COVERED UNDER THE "PROFESSIONAL SERVICES" EXEMPTION OF THE TEXAS DECEPTIVE TRADE ACT. REFER TO TEXAS COURT OF APPEALS CASE IN FORT WORTH, TEXAS "HEAD VS U.S. INSPECT".**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION AGREEMENT**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

**IMPORTANT INSPECTION LIMITATIONS AND DISCLAIMERS (CONT.)**

**FOR EXAMPLE, BUT WITHOUT LIMITATION, RECENT REPAIRS, PAINTING, OR COVERING MAY CONCEAL PRIOR OR PRESENT LEAD DAMAGE WHICH IS NOT REASONABLY OBSERVABLE BY THIS INSPECTOR, AND NO REPRESENTATION OR COMMENT CAN BE MADE.**

**THIS INSPECTION DOES NOT COVER THE POSSIBLE EXISTENCE OF SINK HOLES, SUBTERRANEAN WATER PROBLEMS, OTHER TYPES OF GEOTECHNICAL PROBLEMS CONCERNING THE LAND THAT THE PROPERTY IS LOCATED ON. A FULL EVALUATION OF STUCCO OR EIFS EXTERIOR CLADDING (IF PRESENT) IS NOT WITHIN THE SCOPE OF THIS INSPECTION.**

**NO REPRESENTATION IS MADE AS TO ITEMS NOT SPECIFICALLY COMMENTED UPON. ALL WARRANTIES, EXPRESSED OR IMPLIED, NOT SPECIFICALLY STATED HEREIN, ARE EXCLUDED AND DISCLAIMED. IF A COMMENT IS MADE CONCERNING THE PRESENT CONDITION OF AN ITEM, THE BUYER / CLIENT IS URGED TO CONTACT A QUALIFIED SPECIALIST TO MAKE FURTHER INSPECTIONS OR EVALUATIONS OF THAT ITEM. BUYER / CLIENT MUST NOTIFY ALLIED HOME INSPECTION SERVICES OF ANY COMPLAINTS WITHIN SEVEN (7) DAYS OF THE DATE OF THE INSPECTION AND THEREAFTER ALLOW A PROMPT REINSPECTION OF THE ITEM (S) IN QUESTION, OTHERWISE, ALL CLAIMS FOR DAMAGES, ARISING OUT OF SUCH COMPLAINT, ARE WAIVED BY THE BUYER / CLIENT.**

**IF BUYER / CLIENT INSTITUTES ANY LEGAL ACTION CONCERNING THIS INSPECTION, AND FAILS TO PREVAIL ON ALL OF THE CAUSES OF ACTION ALLEGED, BUYER / CLIENT SHALL BE LIABLE TO ALLIED HOME INSPECTION SERVICES FOR ALL OF ITS ATTORNEY FEES INCURRED IN SUCH LEGAL ACTION. ACTUAL DAMAGES FOR ANY BREACH OF CONTRACT OR WARRANTY, NEGLIGENCE, OR OTHERWISE, ARE LIMITED TO THE AMOUNT OF THE INSPECTION FEE SHOWN HEREON. BUYER / CLIENT, BY ACCEPTING THIS INSPECTION REPORT, OR RELYING ON IT IN ANY WAY, EXPRESSLY AGREES TO THESE LIMITATIONS AND DISCLAIMERS.**

**BUYER / CLIENT AND ALLIED HOME INSPECTION SERVICES AGREE THAT SHOULD A COURT OF COMPETENT JURISDICTION DETERMINE AND DECLARE ANY PORTION OF THIS INSPECTION AGREEMENT VOID, VOIDABLE, OR UNENFORCEABLE, THE REMAINING PROVISIONS AND PORTIONS SHALL REMAIN IN FULL FORCE AND EFFECT.**

**DATED: SEPTEMBER 21, 2011  
SIGNATURES OF BUYER / CLIENT AND JOHN O. FRANZEN WERE ON THE ORIGINAL INSPECTION AGREEMENT.**

**NOTE:  
IF BUYERS /CLIENTS ARE NOT PRESENT DURING THE INSPECTION, A COPY OF THIS INSPECTION AGREEMENT WILL BE EMAILED OR FAXED TO THEM PRIOR TO THE TIME OF THE INSPECTION, SO THAT THEY CAN READ IT CAREFULLY, DATE, SIGN, AND RETURN THE AGREEMENT VIA FAX OR EMAIL.**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION AGREEMENT**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

**STATUS OF PROPERTY AT TIME OF INSPECTION**

<b>APPROX. AGE OF THE PROPERTY?</b> NEW	<b>APPROX. SQUARE FOOTAGE?</b> 1,649 SQ. FT.
<b>IS THE PROPERTY OCCUPIED OR VACANT?</b> VACANT	<b>NO. OF STORIES?</b> ONE
<b>NAME OF BUILDER?</b>	<b>PROPERTY FACES WHICH DIRECTION?</b> EAST
<b>IS ELECTRICITY ON?</b> YES	<b>IS GAS ON?</b> N/A
<b>IS PROPERTY ALL ELECTRIC?</b> YES	<b>IS WATER ON?</b> YES
<b>IS THERE A SPRINKLER SYSTEM?</b> NO	<b>IS THERE A WATER WELL SYSTEM?</b> NO
<b>IS A WOOD SHINGLE ROOF STILL IN PLACE?</b> NO	<b>IS THERE A SEPTIC SYSTEM?</b> NO
<b>ARE THERE ANY SKYLIGHTS?</b> NO	<b>LOCATION OF SKYLIGHTS?</b> N/A
<b>IS THERE A POOL AND / OR SPA?</b> NO	<b>TYPE OF FOUNDATION?</b> SLAB ON GRADE
<b>DATE OF INSPECTION?</b> SEPTEMBER 21, 2011	<b>START TIME OF INSPECTION?</b> 10:45 AM
<b>WEATHER CONDITIONS:</b> CLEAR	<b>END TIME OF INSPECTION?</b> 12:50 PM

**NOTE:**

AIR DRAFTING QUALITY OR ITS ADEQUACY OF THE FIREPLACE (S) ARE NOT TESTED. THE FOLLOWING ITEMS WERE NOT INSPECTED: GAS LINES, OUTDOOR COOKING EQUIPMENT, YARD LIGHTING, FRENCH DRAIN SYSTEMS, SECURITY / FIRE PROTECTION SYSTEMS, WATER WELL SYSTEMS, SEPTIC SEWAGE SYSTEMS, SELF-CLEANING CYCLE ON OVENS, OVEN TIMERS, AND ANY RADIATION LEAKAGE FROM MICROWAVE OVENS. T & P VALVES, ON WATER HEATERS, ARE NOT OPERATED.'

**NOTE:**

THE DETERMINATION, OF THE EXISTENCE OF BROWNFIELDS, SINK HOLES, SUBTERRANEAN WATER PROBLEMS, OR OTHER GEOTECHNICAL TYPE PROBLEMS ON THE SUBJECT PROPERTY OR ADJACENT PROPERTIES, IS NOT WITHIN THE SCOPE OF THIS INSPECTION.

**NOTE:**

IF WOOD SHINGLE ROOF IS STILL IN PLACE UNDER THE COMPOSITION ROOF, BUYER (S) MAY HAVE DIFFICULTY OBTAINING HOMEOWNER'S INSURANCE.

**NOTE:**

IF ALUMINUM BRANCH WIRING IS PRESENT IN THE PROPERTY. BUYER (S) MAY HAVE HAVE DIFFICULTY OBTAINING HOMEOWNER'S INSURANCE.

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**NOTE:**

**THE PURPOSE OF A PROPERTY OR HOME INSPECTION, IS TO INFORM THE BUYER (S) OF THE PRESENT CONDITION OF THE PROPERTY OR DWELLING BASED ON CURRENT BUILDING STANDARDS. THIS INSPECTOR HAS NO AUTHORITY TO REQUIRE ANYONE TO MAKE ANY REPAIRS THAT ARE LISTED IN THIS REPORT.**

**NOTE:**

**INTERNATIONAL RESIDENTIAL CODE (IRC) FOR ONE AND TWO FAMILY DWELLINGS (2000) IS THE STANDARD FOR THE ENTIRE STATE OF TEXAS. CODE COMPLIANCE IN LIFE AND SAFETY ISSUES, DOES NOT APPLY TO EXISTING DWELLINGS BUT DOES APPLY FOR NEW DWELLINGS. REPLACEMENTS OR ADDITIONS, TO AN EXISTING DWELLING, SUCH AS A NEW A/C SYSTEM, ARE REQUIRED TO MEET THE NEW BUILDING CODE.**

**NOTE:**

**A MINIMUM OF 4 INCHES OF SLAB NEEDS TO BE LEFT EXPOSED AND POSITIVE DRAINAGE AWAY FROM THE SLAB NEEDS TO BE MAINTAINED AT ALL TIMES. IF THERE ARE ANY TREES LOCATED WITHIN 5 FEET OF THE FOUNDATION, IT IS RECOMMENDED THAT THE TREES EITHER BE REMOVED OR TREE ROOT BARRIERS BE INSTALLED TO DECREASE THE POSSIBILITY OF FUTURE FOUNDATION PROBLEMS CAUSED BY THE TREE ROOTS. THE INSTALLATION AND USE, OF SOAKER HOSES AROUND THE SLAB, IS STRONGLY RECOMMENDED.**

**NOTE:**

**THE DETERMINATION, OF THE EXISTENCE OF BROWNFIELDS, SINK HOLES, SUBTERRANEAN WATER PROBLEMS, OR OTHER GEOTECHNICAL TYPE PROBLEMS ON THE SUBJECT PROPERTY OR ADJACENT PROPERTIES, IS NOT WITHIN THE SCOPE OF THIS INSPECTION.**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**NOTE:**

**BUYER (S) SHOULD OBTAIN A COPY OF THE BUILDER'S WARRANTY PACKAGE WHICH SHOULD CONTAIN COPIES OF THE WARRANTIES ON THE FOUNDATION, ROOF, A/C & HEATING SYSTEMS, WATER HEATER (S), AND APPLIANCES.**

**NOTE:**

**ALL, OF THE BELOW LISTED REPAIRS, SHOULD BE COMPLETED BY THE BUILDER AT NO COST TO THE BUYER(S):**

- NO. 1            LARGE TRAILER, PARKED INSIDE THE GARAGE, NEEDS TO BE REMOVED FROM THE PROPERTY.**
  
- NO. 2            ALL TRASH & CONSTRUCTION MATERIALS, IN THE GARAGE, NEED TO BE REMOVED AND HAULED AWAY**
  
- NO. 3            CONCRETE GARAGE FLOOR LOOKS VERY ROUGH. THIS FLOOR NEEDS TO BE RESKIMMED.**
  
- NO. 4            CONCRETE GARAGE FLOOR NEEDS TO BE SCRAPED AND WASHED DOWN.**
  
- NO. 5            MISSING GUTTERS, DOWNSPOUTS, AND SPLASH BLOCKS ON ALL FOUR SIDES. SEE APPENDIX B-1 & U-3. REPAIRS ARE NEEDED.**
  
- NO. 6            ANT INFESTATION, AT THE BOTTOM OF THE OVERHEAD GARAGE DOOR, NEEDS REPAIR.**
  
- NO. 7            GALVANIZED - COPPER PIPING CONNECTIONS, AT THE TOP OF THE WATER HEATER, ARE MISSING DIELECTRIC FITTINGS. SEE APPENDIX K-2 & K-3. REPAIRS ARE NEEDED**
  
- NO. 8            VERTICAL FRAME BOARDS, AT THE OVERHEAD GARAGE DOOR, NEED TO BE PAINTED.**
  
- NO. 9            MISSING WINDOW SCREENS IN AT LEAST TWO PLACES. REPAIRS ARE NEEDED**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

- NO. 10**      **THERE ARE APPROXIMATELY THREE WHITE NEUTRAL WIRES COMING OUT OF BREAKERS. THESE WHITE WIRES NEED TO BE TRACED BY LICENSED ELECTRICIAN TO DETERMINE IF THEY ARE REALLY HOT WIRES THAT HAVE NOT BEEN TAGGED AS HOTS, IF THEY ARE REALLY NEUTRAL WIRES, THEN THE BREAKER BOX NEEDS TO BE REWIRED.**
- NO. 11**      **ALL 15 & 20 AMP WALL RECEPTACLES NEED TO BE CHANGED TO TAMPER-RESISTANT TYPE RECEPTACLES. SEE APPENDIX 406.11**
- NO. 12**      **ALUMINUM WIRES, THAT ARE ATTACHED TO THE LUGS IN THE BREAKER BOX, ARE MISSING A PASTE. SEE APPENDIX E110.14**
- NO. 13**      **WIRES, THAT ARE LEAVING THE BREAKER BOX, ARE BUNDLED TOGETHER. THIS IS AN OVER-HEATING ISSUE. THESE WIRES NEED TO BE SPREAD OUT. REPAIRS ARE NEEDED**
- GAPS, UNDER THE FOUNDATION ON THE BACK SIDE, NEED TO BE FILLED AND COMPACTED PROPERLY.**
- NOTE:**  
**IF THIS REPAIR IS NOT DONE PROPERLY, THERE IS A STRONG POSSIBILITY OF FUTURE FOUNDATION SETTLEMENT AND NEEDED REPAIRS.**
- NO. 14**      **GAPS, AROUND THE A/C HOSES WHERE THEY ENTER THE HOUSE BY THE CONDENSER UNIT, NEED TO BE SEALED PROPERLY.**
- NO. 15**      **POWER CORD, AT THE A/C CONDENSER UNIT, IS LAYING ON THE GROUND. THIS POWER CORD NEEDS TO BE ELEVATED.**
- NO. 16**      **LIQUID LINE, AT THE A/C CONDENSER UNIT, IS MISSING A DRYER. REPAIRS ARE NEEDED.**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

- NO. 17            INSULATION IS LAYING IN THE ATTIC ON VENT FAN ASSEMBLIES. THE PRESENT SETUP POSES A FIRE HAZARD. THE INSULATION NEEDS TO BE PULLED BACK FROM THESE AREAS. SEE APPENDIX JJ-4 & S-3.**
  
- NO. 18            SPRINGS, ON THE ATTIC ACCESS LADDER, ARE MISSING SAFETY WIRE.**
  
- NO. 19            WOOD FENCE PICKETS, ON THE NORTH SIDE, ARE BOWED AND DAMAGED IN A NUMBER OF AREAS. REPAIRS ARE NEEDED.**
  
- NO. 20            LARGE TRENCH, IN THE NORTH SIDE YARD, NEEDS TO BE FILLED IN AND SLOPED PROPERLY TO THE FRONT. THIS IS A BREEDING GROUND FOR MOSQUITOES. REPAIRS ARE NEEDED.**
  
- NO. 21            BACK YARD NEEDS TO BE LEVELED AND ALL HOLES AND CREVICES FILLED IN. THE PRESENT SETUP POSES A TRIPPING HAZARD. REPAIRS ARE NEEDED**
  
- NO. 22            SPRAY NOZZLE, AT THE KITCHEN SINK, NEEDS REPAIR OR REPLACEMENT. THE SPRAY NOZZLE WILL NOT RETRACT PROPERLY.**
  
- NO. 23            KITCHEN SINK IS MISSING AN ANTI-SIPHONING DEVICE. IT IS REQUIRED DUE TO THE PRESENCE OF THE SPRAY NOZZLE. SEE APPENDIX N-2.**
  
- NO. 24            ALL, OF THE SMALL BROKEN GLASS SHARDS, N THE CARPET BY THE ENTRYWAY, NEED TO BE VACUUMED UP.**
  
- NO. 25            POWER CORD, TO THE DISPOSAL UNDER THE KITCHEN SINK, NEEDS TO BE ENCLOSED IN A SHIELDED FLEX CONDUIT.**
  
- NO. 27            MISSING OR DAMAGED DOOR STOPS IN SEVERAL AREAS.**
  
- NO. 28            WOOD CLOSET POLES NEED TO BE EITHER STAINED OR PAINTED.**

ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET

ALLIED HOME INSPECTION SERVICES

JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553

800 / 498 - 4498

---

ADDRESS OF PROPERTY:

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**NOTE:**

THE INSPECTION, FOR THE POSSIBLE PRESENCE OF MOLD, FUNGI, OR OTHER MICROBES IS NOT WITHIN THE SCOPE OF THIS INSPECTION. IF THERE IS ANY EVIDENCE OF MOISTURE PENETRATION IN THE HOUSE, IT IS STRONGLY RECOMMENDED THAT THE BUYER (S) HAVE A QUALIFIED LICENSED MOLD INSPECTION COMPANY DO A MOLD INSPECTION ON THE PROPERTY PRIOR TO PURCHASE. BUYER (S) SHOULD ALSO CHECK WITH THEIR HOMEOWNER'S INSURANCE COMPANY TO DETERMINE IF THERE HAVE BEEN ANY PREVIOUS WATER DAMAGE CLAIMS ON THIS PROPERTY.

**NO. 29**

THE TEMPERATURE READINGS ON PAGE 33 OF THIS REPORT, INDICATE THAT THE A/C SYSTEM NEEDS SERVICING.

**NOTE:**

AFTER ALL NEEDED REPAIRS ARE COMPLETED ON THE A/C SYSTEM (S), PAGE 34 OF THIS REPORT, SHOULD BE COMPLETED BY A QUALIFIED AND LICENSED A/C TECHNICIAN.

**NOTE:**

THE CORRECT SIZING, OF THE A/C SYSTEM (S) CAN BE DETERMINED BY THE FOLLOWING:

A. SQUARE FOOTAGE OF AIR CONDITIONED AREA X 20 DIVIDED BY 12,000 = TONS OF A/C.

B. TOTAL SQUARE FOOTAGE OF AIR-CONDITIONED AREA DIVIDED BY 600 = TONS OF A/C

HIGH CEILINGS AND / OR A LOT OF GLASS WINDOWS WILL CHANGE AND HAVE AN EFFECT ON THESE CALCULATIONS

**NO. 30**

SHOWER DOOR, IN THE MASTER BATH, NEEDS TO BE INSTALLED PROPERLY. IT CAME APART IN OUR HANDS WHEN WE TRIED TO OPEN IT. REPAIRS ARE NEEDED

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:            8030 GLADSTONE ST.**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

- NO. 31            GAPS, AT THE SIDES OF THE MASTER BATH SINK COUNTER TOP,  
NEED TO BE REPAIRED.**
  
- NO 32            WALL SWITCHES, IN THE MASTER BATH, CAN BE REACHED WHILE  
STANDING IN THE TUB. THE PRESENT SETUP POSES A SEVERE  
SAFETY HAZARD. THESE WALL SWITCHES NEED TO BE  
RELOCATED AWAY FROM THE TUB.**
  
- NO. 33            OVEN THERMOSTAT IS OFF APPROX. 60 DEGREES ON THE HIGH  
SIDE IN "BAKE" SETTING. THE THERMOSTAT NEEDS TO BE  
ADJUSTED OR REPLACED.**
  
- NO. 34            METAL A/C DRAIN PAN, IN THE ATTIC, IS MISSING A FLOAT SWITCH.  
SEE APPENDIX CC-2. REPAIRS ARE NEEDED.**
  
- NO. 35            BATHTUB, IN THE NO. 2 BATH, IS MISSING A PLUMBING ACCESS  
PANEL. SEE APPENDIX K-2 & K-3. REPAIRS ARE NEEDED**
  
- NO. 36            EXTERIOR BRICK VENEER IS MESSING WEEP HOLES OVER  
WINDOWS AND DOORS. SEE APPENDIX T-3. REPAIRS ARE NEEDED**
  
- NO. 37            AFTER ALL REPAIRS ARE COMPLETED, ENTIRE HOUSE NEEDS A  
FINAL CLEAN INCLUDING WINDOW WASHING.**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**I. STRUCTURAL SYSTEMS**

**A. FOUNDATION**

**DESCRIPTION:**

**MATERIAL USED:      CONCRETE**

**TYPE:                      SLAB ON GRADE**

**METHOD OF INSPECTION: PERIMETER, OF THE FOUNDATION,  
WAS WALKED.**

**NOTE:**

**A SURVEY, OF THE FOUNDATION, WAS DONE TO DETERMINE THE  
DEGREE OF LEVEL USING A "ZIP LEVEL PRO 2000" ELEVATION  
MEASUREMENT SYSTEM**

**NOTE:**

**FOUNDATION APPEARS TO BE PROVIDING PROPER SUPPORT  
FOR THE STRUCTURE AT THE TIME OF THE INSPECTION.**

**NOTE**

**THERE IS NO GUARANTEE ON THE FOUNDATION CONTINUING  
TO BE FUNCTIONAL. THE FOUNDATION MAY DEVELOP ADDITIONAL  
DEFLECTION IN THE FUTURE**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**I. STRUCTURAL SYSTEMS**

**B. GRADING AND DRAINAGE**

**DESCRIPTION:**

**IS THERE POSITIVE DRAINAGE AWAY FROM  
THE SLAB ON ALL FOUR SIDES? NO**

**DOES THE FOUNDATION HAVE A MINIMUM 4-INCH CLEARANCE,  
FROM THE GROUND, ON ALL FOUR SIDES? YES**

**ARE ALL, OF THE WEEP HOMES, AT THE BOTTOM OF THE  
EXTERIOR WALLS, OPEN ON ALL FOUR SIDES? YES**

**ARE THERE ANY RETAINING WALLS PRESENT? NO**

**NOTE:**

**IF DRAINAGE IS NOT POSITIVE (AWAY FROM THE FOUNDATION,  
IT IS RECOMMENDED THAT ELEVATIONS BE  
PERFORMED TO DETERMINE WHAT ADDITIONAL DRAINAGE  
REPAIRS MAY BE NEEDED**

**NOTE:**

**EROSION CONTROL AND EARTH STABILIZATION SYSTEMS  
ARE NOT A PART OF THIS INSPECTION.**

**NOTE:**

**POSITIVE DRAINAGE, AWAY FROM THE FOUNDATION, IS DEFINED  
AS 6 INCHES IN 10 FEET. (5% SLOPE 10 FEET AWAY)**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**I. STRUCTURAL SYSTEMS**

**FOUNDATION MAINTENANCE PROGRAM**

**DRAINAGE:**

**IF WATER IS POOLING NEAR THE FOUNDATION AFTER A HEAVY RAIN, CORRECT THE GRADE SLOPE OR ADD UNDER GROUND DRAINAGE.**

**CHECK THAT PATIOS AND FLATWORK AROUND THE STRUCTURE ARE PROVIDING POSITIVE DRAINAGE AWAY FROM THE FOUNDATION.**

**CHECK THAT FENCES, FLOWERBEDS,, OR EDGING ARE NOT BLOCKING DRAINAGE.**

**CHECK THAT CLOGS OR LEAKS IN ANY EXISTING DOWNSPOUT EXTENSIONS, AREA DRAINS, OR UNDER GROUND DRAINAGE PIPES. IF PRESENT, CLEAN AND REPAIR AS REQUIRED.**

**VEGETATION:**

**CHECK THAT THERE IS NO BROADLEAF TREE (e.g. OAK, ASH, TALLOW, PECAN, AND HACKBERRY, ETC.) CLOSER TO THE FOUNDATION A DISTANCE EQUAL TO THE HEIGHT FO THE TREE, EVEN IF THE TREE IS ON AN ADJACENT PROPERTY. IF THIS EXISTS, BEGIN A PRUNING PROGRAM TO KEEP THE TREE'S CANOPY AT THAT SIZE FOR THE REST OF ITS LIFE. A REASONABLE PRUNING INTERVAL WOULD BE EVERY 2-3 YEARS.**

**CHECK THAT THERE IS NO NEW TREE, OF ANY KIND, COMING UP NEXT TO THE FOUNDATION. IF FOUND, REMOVE IT.**

**CHECK THAT THERE ARE NO SHRUBS NEXT TO THE FOUNDATION THAT HAVE GROWN TO THE POINT WHERE THEY APPROACH A ONE STORY ROOF IN HEIGHT. IF FOUND, CUT THEM BACK TO WINDOW HEIGHT OR REPLACE THEM WITH A SMALLER VARIETY.**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**I. STRUCTURAL SYSTEMS**

**B. GRADING AND DRAINAGE (CONT.)**

**FOUNDATION MAINTENANCE PROGRAM (CONT.)**

**WATER LEAKS:**

**CHECK THAT NO LEAKS HAVE DEVELOPED NEAR THE FOUNDATION, SUCH AS A FAUCET DRIP OR A CONDENSATE DRIP FROM AN AIR CONDITIONING UNIT, PARTICULARLY FROM AN A/C EMERGENCY OVERFLOW PIPE. IF FOUND, REPAIR AS NEEDED.**

**CHECK THAT UNDERGROUND DRAINAGE SYSTEM (IF PRESENT) IS PROPERLY FUNCTIONING. IF IT DOES NOT DRAIN FREELY, INVESTIGATE AND CLEAN AS NEEDED TO ACHIEVE NORMAL FLOW.**

**CHECK THAT SWIMMING POOLS, PONDS, FOUNTAINS, ETC, ARE HOLDING WATER WITHOUT LEAKING. IF SUSPECTED OF LOSING WATER BELOW GRADE, HAVE A POOL-LEAK- DETECTION COMPANY INVESTIGATE, ISOLATE, AND REPAIR THE LEAK.**



**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**D. ROOF STRUCTURE AND ATTIC**

**DESCRIPTION:**

<b>METHOD ATTIC WAS INSPECTED?</b>	<b>ATTIC WAS WALKED</b>
<b>TYPE OF INSULATION MATERIALS IN THE ATTIC (S)?</b>	<b>FIBERGLASS</b>
<b>APPROX. DEPTH OF THE INSULATION?</b>	<b>10 - 12 INCHES</b>
<b>LOCATION OF ATTIC ACCESS OPENING (S)?</b>	<b>INSIDE GARAGE</b>
<b>TYPE (S) OF STATIC ATTIC VENTILATION?</b>	<b>SOFFIT VENTS ROOF VENTS, RIDGE VENTS</b>
<b>IS THERE A MECHANICAL VENTILATION SYSTEM PRESENT IN THE ATTIC?</b>	<b>NO</b>
<b>ARE THERE ATTIC AREAS MISSING INSULATION AT CONDITIONED SURFACES?</b>	<b>NO</b>
<b>ARE THERE ANY DAMAGED FASCIA BOARDS, SOFFIT BOARDS, OR SOFFIT VENTS?</b>	<b>NO</b>
<b>ARE SOFFIT VENTS PRESENT ON AT LEAST 3 EAVES?</b>	<b>YES</b>

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**I. STRUCTURAL SYSTEMS (CONT.)**

**E. WALLS (INTERIOR AND EXTERIOR)**

**DESCRIPTION:**

**TYPE (S) OF EXTERIOR WALLS?**

**BRICK VENEER & SIDING**

**TYPE )S) OF INTERIOR WALLS?**

**DRYWALL**

**EXTERIOR WALL STRUCTURE?**

**WOOD FRAME, BRICK VENEER**

**F. CEILINGS AND FLOORS**

**DESCRIPTION:**

**CEILING FINISH (S) ?**

**DRYWALL**

**FLOOR SURFACES (S)?**

**CARPET, TILE**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**I. STRUCTURAL SYSTEMS (CONT.)**

**G. DOORS (INTERIOR AND EXTERIOR)**

**DESCRIPTION:**

<b>NUMBER OF GARAGE DOORS?</b>	<b>ONE</b>
<b>GARAGE DOOR MATERIAL?</b>	<b>ALUMINUM</b>
<b>ARE ELECTRIC GARAGE DOOR OPENERS PRESENT?</b>	<b>NO</b>
<b>INTERIOR DOOR TYPE?</b>	<b>HOLLOW CORE WOOD</b>

**NOTE:**

**IT WAS NOT DETERMINED IF THE ACCESS DOOR BETWEEN THE HOUSE AND GARAGE IS A PROPERLY FIRE-RATED TYPE DOOR.**

ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET

ALLIED HOME INSPECTION SERVICES

JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553

800 / 498 - 4498

---

ADDRESS OF PROPERTY:

---

SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)

I. STRUCTURAL SYSTEMS (CONT.)

H. WINDOWS

DESCRIPTION:

WINDOW STYLE (S)?

DOUBLE - SINGLE HUNG - DOUBLE PANE

NOTE:

NOT ALL WINDOWS WERE INSPECTED FOR OPERATION. ONLY A FEW, ACCESSIBLE WINDOWS, WERE CHECKED. THE FLASHING DETAILS ARE CONCEALED AND NOT ACCESSIBLE. NO COMMENT IS MADE ON THE INTEGRITY OF THE FLASHING DETAILS. A LEAK CHECK WOULD BE REQUIRED ON THE FLASHING DETAILS WHICH IS NOT WITHIN THE SCOPE OF THIS INSPECTION, TO DETERMINE THEIR INTEGRITY.

DO ANY OF THE ESCAPE WINDOW SILLS, IN THE BEDROOMS, EXCEED A MAXIMUM HEIGHT OF 44 INCHES FROM THE FLOOR?

NO

DO ANY OF THE ESCAPE WINDOWS, IN THE BEDROOMS, NOT MEET A MINIMUM SIZE OF 5.7 SQUARE FEET?

NO

ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET

ALLIED HOME INSPECTION SERVICES

JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553

800 / 498 - 4498

---

ADDRESS OF PROPERTY:

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**I. STRUCTURAL SYSTEMS (CONT.)**

**H. WINDOWS**

**NOTE:**

**THE PRESENCE, OF SAFETY GLASS, IS REQUIRED IN  
HAZARDOUS AREAS SUCH AS THE FOLLOWING:**

**ENTRY AND EXIT DOORS EXCEPT JALOUSIES**

**FIXED AND SLIDING PANELS OF SLIDING PATIO DOORS**

**ASSEMBLIES AND PANELS IN SWINGING DOORS**

**DOORS AND ENCLOSURES FOR HOT TUBS, WHIRLPOOLS.  
SAUNAS, STEAM ROOMS, BATHTUBS, AND SHOWERS**

**IN ANY EXTERIOR WALL, WHERE THE BOTTOM OF THE  
EXPOSED EDGE OF GLASS IS LESS THAN 60 INCHES  
MEASURED ABOVE ANY STANDING OR WALKING SURFACE**

**EXPOSED AREA OF AN INDIVIDUAL PANE GREATER THAN  
NINE (9) SQUARE FEET IN SIZE.**

**THE INSPECTOR WAS NOT ABLE TO DETERMINE IF THE  
EXISTING GLASS IN THESE AREAS (IF PRESENT) WAS  
SAFETY GLASS.**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**DESCRIPTION:**

<b>TYPE OF KITCHEN COUNTER TOPS?</b>	<b>GRANITE</b>
<b>TYPE OF BATH SINK COUNTER TOPS?</b>	<b>MARBLE</b>
<b>TYPE OF DRIVEWAY?</b>	<b>CONCRETE</b>
<b>TYPE OF FRONT WALKWAY?</b>	<b>CONCRETE</b>
<b>TYPE OF PATIO?</b>	<b>CONCRETE</b>

**NOTE:**

**A REPRESENTATIVE NUMBER OF CABINET DOORS AND  
DRAWERS WERE OPERATED.**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**II ELECTRICAL SYSTEMS**

**A. SERVICE ENTRANCE AND PANELS**

<b>TYPE OF SERVICE WIRING?</b>	<b>STRANDED - ALUMINUM</b>	
<b>TYPE OF BRANCH WIRING?</b>	<b>ROMEX - COPPER</b>	
<b>VOLTAGE RATING OF THE MAIN SERVICE?</b>	<b>120 / 220 VOLTS</b>	
<b>AMPERAGE RATING OF THE MAIN SERVICE?</b>	<b>150 AMPS</b>	
<b>IS ALUMINUM BRANCH WIRING PRESENT?</b>	<b>NO</b>	
<b>LOCATION (S) OF MAIN BREAKER BOX (S)?</b>	<b>OUTSIDE SOUTH WALL</b>	
<b>LOCATION (S) OF SUB-PANEL BOX (S)?</b>	<b>N/A</b>	
<b>BREAKER BOX MANUFACTURER (S)?</b>	<b>SQUARE D</b>	
<b>ARE SMOKE ALARMS PRESENT INSIDE ALL SLEEPING ROOMS?</b>		<b>YES</b>
<b>TYPE AND LOCATION OF SERVICE DROP?</b>	<b>ABOVE GROUND</b>	
<b>LOCATION OF SERVICE GROUNDING?</b>	<b>SOUTH EAVE</b>	

**B. BRANCH CIRCUITS, CONNECTED DEVICES, AND FIXTURES**

**DESCRIPTION:**

<b>TYPE OF HOUSE WIRING?</b>	<b>COPPER - ROMEX</b>	
<b>ARE GFCIs PRESENT ON KITCHEN, BATH, WETBAR, GARAGE, AND EXTERIOR OUTLETS?</b>	<b>YES</b>	
<b>ARE BEDROOM OUTLETS CONNECTED TO ARC-FAULT BREAKERS IN THE BREAKER BOX?</b>	<b>YES</b>	
<b>ARE OUTLETS GROUNDED?</b>	<b>YES</b>	

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**II ELECTRICAL SYSTEMS (CONT.)**

**B. BRANCH CIRCUITS, CONNECTED DEVICES, AND FIXTURES**

**SMOKE ALARMS:**

**NOTE:**

**SINGLE AND MULTI-STATION SMOKE ALARMS SHALL BE  
INSTALLED IN THE FOLLOWING LOCATIONS:**

**IN EACH SLEEPING ROOM**

**OUTSIDE EACH SEPARATE SLEEPING AREA IN THE IMMEDIATE  
VICINITY OF THE BEDROOMS.**

**ON EACH ADDITIONAL STORY OF THE DWELLING EXCLUDING  
UNINHABITABLE ATTICS**

**MULTI ALARMS ARE NOT INTERCONNECTED. WHEN MORE THAN  
ONE SMOKE ALARM IS REQUIRED TO BE INSTALLED WITHIN  
AN INDIVIDUAL DWELLING UNIT, THE ALARM DEVICES SHALL BE  
INTERCONNECTED IN SUCH A MANNER THAT THE ACTUATION OF  
ONE ALARM WILL ACTIVATE ALL OF THE ALARMS IN THE INDIVIDUAL  
UNIT. (IRC-R317.1). IT SHOULD BE NOTED THE SPECIFIC LOCATION  
REQUIREMENTS OF THE SMOKE ALARMS WERE NOT INSPECTED  
PER NFPA 72-11.8.3.5.**

**NOTE:**

**SMOKE ALARMS WERE NOT TESTED NOR OPERATED.**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**III HEATING, VENTILATION, AND AIR CONDITIONING SYSTEMS**

**A. HEATING EQUIPMENT**

**DESCRIPTION:**

<b>NUMBER OF HEATING SYSTEMS?</b>	<b>ONE</b>
<b>TYPE OF HEATING SYSTEM?</b>	<b>FORCED AIR</b>
<b>ENERGY SOURCE?</b>	<b>ELECTRIC</b>
<b>LOCATION (S) OF HEATING SYSTEMS?</b>	<b>ATTIC</b>
<b>APPROX. AGE OF THE HEATING SYSTEM (S)?</b>	<b>NEW</b>
<b>TYPE OF WARM AIR DISTRIBUTION SYSTEM?</b>	<b>DUCTWORK</b>
<b>TYPE OF GAS LINE (S) TO THE HEATING SYSTEM (S)?</b>	<b>N/A</b>
<b>ARE ANY OF THE GAS LINES, TO THE HEATING SYSTEMS, GALVANIZED STEEL?</b>	<b>N/A</b>
<b>IS THERE A ONE INCH CLEARANCE TO COMBUSTIBLES WHERE THE FURNACE FLUES GO THROUGH THE ROOF?</b>	<b>N/A</b>

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**III HEATING, VENTILATION, AND AIR CONDITIONING SYSTEMS (CONT.)**

**B. COOLING EQUIPMENT**

**DESCRIPTION:**

<b>NUMBER OF COOLING SYSTEM (S)?</b>	<b>ONE</b>
<b>SIZE (S) OF THE COOLING SYSTEMS?</b>	<b>3 TON</b>
<b>LOCATION (S) OF THE CONDENSER UNIT (S)?</b>	<b>BACK</b>
<b>LOCATION (S) OF THE EVAPORATOR COIL (S)?</b>	<b>ATTIC</b>
<b>TYPE OF COOL AIR DISTRIBUTION SYSTEM:</b>	<b>DUCTWORK</b>
<b>APPROX. AGE (S) OF THE A/C SYSTEM (S)?</b>	<b>NEW</b>
<b>ENERGY SOURCE?</b>	<b>ELECTRIC</b>

ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET

ALLIED HOME INSPECTION SERVICES

JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553

800 / 498 - 4498

---

ADDRESS OF PROPERTY:

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**III HEATING, VENTILATION, AND AIR CONDITIONING SYSTEMS (CONT.)**

**B. COOLING EQUIPMENT**

**NOTE:**

AS OF JANUARY 23, 2006, THE US DEPARTMENT OF ENERGY HAS MANDATED THAT ALL MANUFACTURED A/C UNITS WILL BE A 13 SEER. WHEN 10 SEER PARTS ARE GONE, THEY ARE GONE. THE HOMEOWNER WILL HAVE TO PURCHASE A 13 SEER COMPRESSOR. THE UNKNOWN IS WHETHER THE EVAPORATOR COIL WILL ALSO HAVE TO BE REPLACED. THEY ARE WORKING ON AN "ADAPTER" TO ALLOW THE TWO TO "SPEAK" TO EACH OTHER. IT'S AVAILABILITY AND EFFICIENCY ARE NOT KNOWN YET. VISA VERSA, IT IS ALSO TRUE IF THE EVAPORATOR COIL HAS TO BE REPLACED, THIS MEANS THAN AN INSPECTION REPORT THAT INDICATES A BAD COMPRESSOR MAY NOT ONLY REQUIRE A MORE EXPENSIVE 13 SEER UNIT BUT MAY ALSO REQUIRE STRUCTURAL AND SPACE CHANGES TO ACCOMMODATE THE LARGER AND HEAVIER 13 SEER UNIT. IT MAY ALSO REQUIRE THAT THE EVAPORATOR COIL TO ALSO BE REPLACED.

**NOTE:**

BUYERS SHOULD VERIFY WITH THE BUILDER, THAT ALL A/C SYSTEMS ARE AT LEAST A 13 SEER.

**C. DUCT SYSTEM, CHASES AND VENTS**

**DESCRIPTION:**

**TYPE OF DUCTWORK:** FLEX

**NUMBER OF A/C RETURN DUCTS?** TWO

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**IV PLUMBING SYSTEMS**

**A. WATER SUPPLY SYSTEM AND FIXTURES**

<b>WATER SUPPLY SOURCE?</b>	<b>PUBLIC WATER SUPPLY</b>
<b>TYPE OF SERVICE PIPE TO HOUSE?</b>	<b>UNKNOWN</b>
<b>TYPE OF SUPPLY LINES?</b>	<b>GALVANIZED, COPPER, &amp; PLASTIC</b>
<b>TYPE OF DRAIN LINES?</b>	<b>PVC</b>
<b>LOCATION OF MAIN WATER SHUTOFF VALVE?</b>	<b>NORTH SIDE</b>
<b>TYPE OF VENT PIPING MATERIALS?</b>	<b>PLASTIC</b>
<b>LOCATION OF GAS LINE MAIN SHUTOFF VALVE?</b>	<b>N/A</b>

**NOTE:**

**IF WALK-IN SHOWERS ARE PRESENT, AND DWELLING IS OLDER THAN 10 YEARS AND / OR HAS BEEN VACANT FOR A PERIOD OF TIME, IT IS STRONGLY RECOMMENDED THAT A LICENSED PLUMBER PERFORM A SHOWER PAN LEAK TEST ON THE SHOWER (S) PRIOR TO CLOSING.**

**NOTE:**

**POLYBUTYLENE PIPING CAN BE IDENTIFIED BY BEING EITHER BLUE, GRAY, OR BLACK IN COLOR AND MAY HAVE THE NAMES VANGUARD OR QUEST STAMPED ON THE PIPING. IF PRESENT, THESE TYPE OF WATER LINES NEED TO BE REPLACED SINCE THEY HAVE A HIGH FAILURE RATE.**

**NOTE:**

**IT WAS NOT DETERMINED THE PRESENCE OR ABSENCE OF AIR ADMITTANCE VALVES AT ALL PLUMBING FIXTURES. IT WAS NOT DETERMINED IF THESE AIR ADMITTANCE VALVES ARE OPERATING PROPERLY.**

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

---

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**IV PLUMBING SYSTEMS (CONT.)**

**A. WATER SUPPLY SYSTEM AND FIXTURES (CONT.)**

**NOTE:**

**SHUTOFF VALVES, AT THE HOUSE AND UNDER KITCHEN, WETBAR, COMMODES, AND BATH SINKS, ARE NOT OPERATED. IT WAS NOT DETERMINED IF THEY OPEN AND CLOSE PROPERLY. IF PROPERTY IS MORE THAN 10 YEARS OLD, THERE IS A STRONG POSSIBILITY THAT SOME OF THESE SHUTOFF VALVES WILL NOT OPEN OR CLOSE PROPERLY AND WILL HAVE TO BE REPLACED.**

**B. DRAINS, WASTES, VENTS**

**DESCRIPTION:**

<b>TYPE OF WASTE SYSTEM?</b>	<b>PUBLIC SEWER SYSTEM</b>
<b>TYPE (S) OF DRAIN LINES?</b>	<b>PVC</b>
<b>LOCATION OF MAIN CLEANOUT?</b>	<b>FRONT</b>

**NOTE:**

**WASHING MACHINE (S) ARE NOT OPERATED DURING THE INSPECTION. NO DETERMINATION WAS MADE AS TO WHETHER THE WASHING MACHINE DRAIN LINE IS OPERABLE.**

**NOTE:**

**OVERFLOW DRAINS, ON SINKS AND TUBS, ARE NOT OPERATED. IT WAS NOT DETERMINED IF THEY DRAIN PROPERLY.**

ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET

ALLIED HOME INSPECTION SERVICES

JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553

800 / 498 - 4498

ADDRESS OF PROPERTY:

SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)

A. WATER SUPPLY SYSTEM AND FIXTURES (CONT.)

C. WATER HEATING EQUIPMENT

DESCRIPTION:

NO. OF WATER HEATERS? ONE  
ENERGY SOURCE? ELECTRIC  
LOCATION (S) OF THE WATER HEATER (S) INSIDE GARAGE  
GAS LINES? N/A  
APPROX. AGE (S) OF THE WATER HEATER (S)? NEW

IS THERE A DRAIN PAN UNDER EACH OF THE WATER HEATER (S)? YES  
(SIZE REQUIREMENT OF THE DRAIN PAN IS 24-GAUGE & 1 1/2 INCHES DEEP.)

IS THERE A ONE INCH CLEARANCE TO COMBUSTIBLES WHERE THE WATER HEATER FLUES GO THROUGH THE ROOF? N/A

NOTE:  
(T&P) TEMPERATURE AND PRESSURE VALVE (S) ON THE WATER HEATER (S) ARE NOT OPERATED.

J. DRYER VENTS

DESCRIPTION:

LOCATION OF THE DRYER VENT? UTILITY ROOM  
IS DRYER VENT LOCATED ON AN INTERIOR WALL? NO  
IS ANY SECTION, OF THE DRYER VENT, ROUTED VERTICALLY? NO

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

800 / 498 - 4498

**ADDRESS OF PROPERTY:**

**NOTE:  
A SURVEY, OF THE FOUNDATION, WAS DONE TO DETERMINE THE  
DEGREE OF LEVEL USING A "ZIP LEVEL PRO 2000" ELEVATION  
MEASUREMENT SYSTEM**

<b>DOWNSTAIRS</b>	<b>LOCATION</b>	<b>TYPE OF FLOOR SURFACE</b>	<b>READING (IN INCHES)</b>
<b>BASE</b>	<b>LIVING ROOM - NORTH WALL</b>	<b>CARPET</b>	<b>0.0</b>
<b>1</b>	<b>ENTRYWAY - BY FRONT DOOR</b>	<b>TILE</b>	<b>-1.1</b>
<b>2</b>	<b>LIVING ROOM- SE CORNER</b>	<b>CARPET</b>	<b>-0.7</b>
<b>3</b>	<b>LIVING ROOM- SW CORNER</b>	<b>CARPET</b>	<b>-0.8</b>
<b>4</b>	<b>KITCHEN - SE CORNER</b>	<b>TILE</b>	<b>-0.7</b>
<b>5</b>	<b>KITCHEN - SW CORNER</b>	<b>TILE</b>	<b>-0.5</b>
<b>6</b>	<b>BREAKFAST AREA - SW CORNER</b>	<b>TILE</b>	<b>-1.2</b>
<b>7</b>	<b>BREAKFAST AREA - BY EXIT DOOR</b>	<b>TILE</b>	<b>-1.3</b>
<b>8</b>	<b>UTILITY ROOM - SW CORNER</b>	<b>TILE</b>	<b>-1.3</b>
<b>9</b>	<b>UTILITY ROOM - NW CORNER</b>	<b>TILE</b>	<b>-1.0</b>
<b>10</b>	<b>FRONT BEDROOM - SE CORNER</b>	<b>CARPET</b>	<b>-0.5</b>
<b>11</b>	<b>FRONT BEDROOM - NE CORNER</b>	<b>CARPET</b>	<b>-1.1</b>
<b>12</b>	<b>NO. 2 BATH - BY TUB</b>	<b>TILE</b>	<b>-0.8</b>
<b>13</b>	<b>MIDDLE BEDROOM - NE CORNER</b>	<b>CARPET</b>	<b>-0.6</b>
<b>14</b>	<b>MIDDLE BEDROOM - NW CORNER</b>	<b>CARPET</b>	<b>-0.7</b>
<b>15</b>	<b>MASTER BEDROOM - SW CORNER</b>	<b>CARPET</b>	<b>-0.6</b>
<b>16</b>	<b>MASTER BEDROOM - NW CORNER</b>	<b>CARPET</b>	<b>0.2</b>
<b>17</b>	<b>MASTER BEDROOM - NE CORNER</b>	<b>CARPET</b>	<b>-0.5</b>
<b>18</b>	<b>M. BATH CLOSET - OUTSIDE WALL</b>	<b>CARPET</b>	<b>-0.8</b>
<b>19</b>	<b>MASTER BATH - UNDER WINDOW</b>	<b>TILE</b>	<b>-0.9</b>

**NOTE:  
THE ENGINEERING STANDARD / GUIDELINE, FOR THE HOUSTON AREA, IS ANYTHING  
UNDER 2.0 INCHES UP OR DOWN FROM A CENTER POINT, IS STILL FUNCTIONAL  
STATE CODE STATES THAT THE MAXIMUM ALLOWABLE LIVE LOAD DEFLECTION  
IS L / 360 ( 1 INCH IN 30 FEET). A DIFFERENTIAL OF 1 1/2 INCHES OR MORE FROM  
A PLUS NUMBER TO A MINUS NUMBER MAY INDICATE SIGNIFICANT FOUNDATION  
MOVEMENT.**



ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET

ALLIED HOME INSPECTION SERVICES

JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553

800 / 498 - 4498

ADDRESS OF PROPERTY:

SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)

III HEATING, VENTILATION, AND AIR CONDITIONING SYSTEMS (CONT.)

B. COOLING EQUIPMENT (CONT.)

AIR CONDITIONING EQUIPMENT CHECK LIST

INDOOR EQUIPMENT:

MAKE: TRANE	SIZE: 3__ TON	THIS A/C UNIT SERVES: ENTIRE HOUSE			
EVAPORATOR ENTERING AIR TEMP?	A. DRY BULB?	78.30	C. WET BULB?	52.90	
EVAPORATOR LEAVING AIR TEMP?	B. DRY BULB?	66.50	D. WET BULB?	50.60	
	SPLIT? E.	11.80	F.	2.30	

NOTE:

DRY BULB SPLIT SHOULD BE WITHIN 13 TO 18 DEGREES?  
WET BULB SPLIT SHOULD BE WITHIN 8 TO 10 DEGREES?

OUTDOOR EQUIPMENT:

G. SUCTION LINE TEMP?	85.30	I. CONDENSER LEAVING AIR TEMP?	102.20
H. LIQUID LINE TEMP?	89.00	J. CONDENSER ENTERING AIR TEMP?	81.70
		K. CONDENSER HEAT RISE? (I LESS J)	20.50

NOTES:

SUCTION LINE TEMPERATURE (G) SHOULD BE 10 TO 20 DEGREES COOLER THAN THE INDOOR DRY BULB LEAVING TEMPERATURE (B).  
LIQUID LINE TEMPERATURE (H) SHOULD BE 3 TO 7 DEGREES WARMER THAN THE CONDENSER ENTERING AIR TEMPERATURE (J).  
CONDENSER HEAT RISE (K) SHOULD BE WITHIN A 10 TO 20 DEGREE RANGE  
OUTDOOR TEMPERATURES BELOW 55 DEGREES AND ABOVE 95 DEGREES WILL CAUSE EXPECTED TEMPERATURES TO VARY.

**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

**ADDRESS OF PROPERTY:**

---

**SUMMARY OF "NOT FUNCTIONING" OR "IN NEED OF REPAIR" ITEMS (CONT.)**

**III HEATING, VENTILATION, AND AIR CONDITIONING SYSTEMS (CONT.)**

**B. COOLING EQUIPMENT (CONT.)**

**AIR CONDITIONING EQUIPMENT CHECK LIST**

**INDOOR EQUIPMENT:**

<b>MAKE:</b>	<b>SIZE: _____ TON</b>	<b>THIS A/C UNIT SERVES:</b>
<b>EVAPORATOR ENTERING AIR TEMP?</b>	<b>A. DRY BULB?</b>	<b>C. WET BULB?</b>
<b>EVAPORATOR LEAVING AIR TEMP?</b>	<b>B. DRY BULB?</b>	<b>D. WET BULB?</b>
	<b>SPLIT? E.</b>	<b>F.</b>

**NOTE:**  
**DRY BULB SPLIT SHOULD BE WITHIN 13 TO 18 DEGREES?**  
**WET BULB SPLIT SHOULD BE WITHIN 8 TO 10 DEGREES?**

**OUTDOOR EQUIPMENT:**

<b>G. SUCTION LINE TEMP?</b>	<b>I. CONDENSER LEAVING AIR TEMP?</b>
<b>H. LIQUID LINE TEMP?</b>	<b>J. CONDENSER ENTERING AIR TEMP?</b>
	<b>K. CONDENSER HEAT RISE? (I LESS J)</b>

**NOTES:**  
**SUCTION LINE TEMPERATURE (G) SHOULD BE 10 TO 20 DEGREES COOLER THAN THE INDOOR DRY BULB LEAVING TEMPERATURE (B).**  
**LIQUID LINE TEMPERATURE (H) SHOULD BE 3 TO 7 DEGREES WARMER THAN THE CONDENSER ENTERING AIR TEMPERATURE (J).**  
**CONDENSER HEAT RISE (K) SHOULD BE WITHIN A 10 TO 20 DEGREE RANGE**  
**OUTDOOR TEMPERATURES BELOW 55 DEGREES AND ABOVE 95 DEGREES WILL CAUSE EXPECTED TEMPERATURES TO VARY.**

ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION REPORT COMMENT SHEET

ALLIED HOME INSPECTION SERVICES

JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553

800 / 498 - 4498

ADDRESS OF PROPERTY:

PHOTO NO. 1

FRONT



PHOTO NO. 2

ELECTRIC WATER HEATER  
IN GARAGE



PHOTO NO. 3  
WATER HEATER PIPING  
MISSING DIELECTRIC FITTINGS



PHOTO NO. 4  
VERTICAL GARAGE DOOR  
FRAME BOARDS NEED TO BE PAINTED



ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION PHOTOS

ALLIED HOME INSPECTION SERVICES

JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553

800 / 498 - 4498

ADDRESS OF PROPERTY:

PHOTO NO. 5

GAPS UNDER THE BACK  
CONCRETE PATIO



PHOTO NO. 6

SOUTH EAVE MISSING  
GUTTERS




PHOTO NO. 7

GAPS, N GROUND, BY BACK  
SIDE SLAB



PHOTO NO. 8

DRAINAGE PROBLEM ON  
NORTH SIDE OF HOUSE



ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION PHOTOS

ALLIED HOME INSPECTION SERVICES

JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553

800 / 498 - 4498

ADDRESS OF PROPERTY:

PHOTO NO. 9

TREE LIMBS OVER ROOF



PHOTO NO. 10

DAMAGED FENCE PICKETS  
ON NORTH SIDE



PHOTO NO. 11

ELECTRICAL WEATHER HEAD  
AT SOUTH FRONT CORNER



PHOTO NO. 12

BREAKER BOX ON OUTSIDE  
SOUTH WALL



**ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION PHOTOS**

**ALLIED HOME INSPECTION SERVICES**

**JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553**

**800 / 498 - 4498**

**ADDRESS OF PROPERTY:**

**PHOTO NO. 13      GAPS, AT THE SIDES OF  
SINK COUNTER TOP IN M. BATH**



**PHOTO NO. 14      KITCHEN SINK MISSING  
ANTI-SIPHONING DEVICE**



**PHOTO NO. 15      SHOWER DOOR, IN M. BATH,  
NEEDS TO BE INSTALLED PROPERLY**



**PHOTO NO. 16      WALL SWITCHES TOO CLOSE  
TO SHOWER IN M. BATH.**



ADDENDUM TO PROPERTY INSPECTION REPORT  
PROPERTY INSPECTION PHOTOS

ALLIED HOME INSPECTION SERVICES

JOHN O. FRANZEN  
LICENSED BUILDING INSPECTOR  
T.R.E.C. # 1553

800 / 498 - 4498

ADDRESS OF PROPERTY:

PHOTO NO. 17

A/C - FURNACE UNIT IN ATTIC



PHOTO NO. 18

METAL A/C DRAIN PAN  
MISSING FLOAT SWITCH



PHOTO NO. 19

INSULATION LAYING ON  
BATH VENT FAN ASSEMBLIES



PHOTO NO. 20

ATTIC ACCESS LADDER IN  
GARAGE



## **TEXAS REAL ESTATE CONSUMER NOTICE CONCERNING HAZARDS OR REPAIRS**

Each year, Texans sustain property damage and are injured by accidents in the home. While some accidents may not be avoidable, many other accidents, injuries, and deaths may be avoided through the identification and repair of certain hazardous conditions. Examples of such hazards include:

- \* Improperly installed or missing ground fault circuit protection (GFCI) devices for electrical receptacles in garages, bathrooms, kitchens, and exterior areas.
- \* Improperly installed or missing arc-fault protection (AFCI) devices for electrical receptacles in family rooms, dining rooms, living rooms, parlors, libraries, dens, bedrooms, sunrooms, recreation rooms, closets, hallways, or similar rooms or areas.
- \* ordinary glass in locations where modern construction techniques call for safety glass
- \* the lack of the safety features such as smoke alarms, fire-rated doors in certain locations, and functional escape and rescue openings in bedrooms.
- \* excessive spacing between balusters on stairways and porches
- \* improperly installed appliances
- \* improperly installed or defective safety devices
- \* lack of electrical bonding and grounding

To ensure that consumers are informed of hazards such as these, the Texas Real Estate Commission (TREC) has adopted Standards of Practice requiring licensed inspectors to report these conditions as "Deficient" when performing an inspection for a buyer or seller, if they can be reasonably determined.

These conditions may not have violated building codes or common practices at the time of the construction of the home, or they may have been "grandfathered" because they were present prior to the adoption of codes prohibiting such conditions. While the TREC Standards of Practice do not require inspectors to perform a code compliance inspection, TREC considers the potential for injury or property loss from the hazards addressed in the Standards of Practice to be significant enough to warrant this notice.

Contract forms developed by TREC for use by its real estate licensees also inform the buyer of the right to have the home inspected and can provide an option clause permitting the buyer to terminate the contract within a specified time. Neither the Standards of Practice nor the TREC contract forms require a seller to remedy conditions revealed by the inspection. The decision to correct a hazard or any deficiency identified in an inspection report is left to the parties to the contract for the sale or purchase of the home.

**FORM OP-1**